

Interference caused by LTE base station optical module failure



Overview

Symptoms: Gradual increase in Bit Error Rate (BER), reduced optical power output (Tx), decreased receiver sensitivity (Rx), complete loss of light transmission or reception. Often causes intermittent issues before total failure. Interference can originate from neighboring cells, other electronic devices, or environmental factors, leading to reduced data rates, increased latency, and overall poor network. The results of this alarms was restarting of the RF unit. After combining the RRU log analysis and the alarm of the optical module, the radio frequency maintenance link is triggered by the power-off of the RRU board, as shown in the following screenshot. This type of test has been in use for 15 years or more within the OEM industry throughout the world. Monitor DOM/DDM Data: Utilize Digital Optical Monitoring (DOM) or. Intermodulation interference is generally caused by the fact that the Intermodulation signal transmitted by nearby radio equipment falls into the frequency band received by the TD-LTE base station.



Article Content

LTE Interference: Mitigating Challenges for Optimal Performance

Conclusion LTE interference poses significant challenges to maintaining high-quality mobile connectivity. However, with advanced interference mitigation techniques and continuous

Description and symptoms Fault Failure in optical interface 3030 is ...

If none of these actions help, perform the following steps on site, until the issue is resolved: Procedure 1 Check the cables between the system module and radio module.

External Interferences Detection by Examples in LTE

Inter-band interference: Interfering signals are generated out of the receive frequency band. However, the receiver receives out-of-band signals

External Interferences Detection by Examples in LTE

35 External Interferences Detection by Examples in LTE Networks for 4G and 5G Networks Efficient Deployments Eric Michel Deussom Djomadji

GTP-U Path Failure Troubleshooting Guide

This document provides information about common 4G alarms, their causes, and troubleshooting steps. The 7100 alarm occurs when the RF module is not

Base Station Alarm Handling Guide | PDF | Lte

Base Station Alarm and Notification Handling Reference (GULI) - Free download as Excel Spreadsheet (.xls / .xlsx), PDF File (.pdf), Text File (.txt) or read online for

Main causes of optical module failure and protective

Optical modules in the application must have standardized operating methods, any irregular action may cause hidden damage or permanent failure.

Common fault solutions for optical fiber modules

Overheating is a common fault in optical fiber modules that can be caused by excessive power, poor ventilation, or ambient temperature. Solution: To prevent overheating, it is important to

Interference optimization and mitigation for LTE networks

Also, interference regeneration and cancelation is mentioned and indicators of signal quality in LTE are named. In the end, a simple MATLAB simulation of the impact of interferences on the throughput is

LTE Interference: Mitigating Challenges for Optimal Performance

However, one of the challenges in maintaining high-quality LTE performance is managing interference. This article explores what LTE interference is, how it affects mobile networks,

passive intermodulation troubleshooting | Anritsu America

Care must be exercised because external interference devices can limit the quality of the testing. Antennas should be pointed facing clear sky with no metallic objects nearby.

General Failure Mode Classification and Analysis of

The low saturation light power caused by the multi-line and APD temperature characteristics is the two failure modes when the high-Speed

LTE Interference troubleshooting guide | PDF

It describes techniques like RSSI analysis, frequency scanning, interference detection tests, and DTP testing to identify issues like passive intermodulation

BBU Optical Module Transmit/Receive Fault

After combining the RRU log analysis and the alarm of the optical module, the radio frequency maintenance link is triggered by the power-off of the RRU board, as shown in the following screenshot.

LTE Service Affecting Alarm

The local base station releases the UEs involved in the inter-base station handover procedure on the correlated X2 interface. Before the alarm is cleared, station cannot allow the inter-base station

Identifying External Interference at Co-Located Cell Sites

However, identifying the root cause of interference is not so trivial; it requires engineers to diligently inspect all aspects of a base station, including internal and external sources, including co-located

Demystifying Optical Transceiver Failures: Common

explores frequent optical transceiver issues and offers practical solutions, and highlight how LINK-PP optical module can mitigate risks.

LTE Signaling, Troubleshooting, and Optimization

LTE Signaling, Troubleshooting and Optimization is the Long Term Evolution successor to the previous Wiley books UMTS Signaling and UMTS Performance Measurement.

S1 Control Plane Transmission Issues | PDF

The document outlines troubleshooting principles for LTE FDD eNodeB, focusing on network management, hardware, and service issues. It details common

5G NR Physical Layer Failures: Root Causes and Solutions

Explore common 5G NR physical layer test failures, their root causes like interference and weak signals, and practical solutions for optimization.

Passive Intermodulation (PIM) Effects in Base Stations

Second, with the explosive growth in the density and diversity of base station towers, we are seeing a whole new range of challenges caused by particular

Radar interference into LTE base stations in the 3.5 GHz band

Abstract We study the interference from a rotating shipborne radar system that spectrally and spatially coexists with a Long Term Evolution (LTE) cellular communications network in the 3.5

Research on Interference of LTE Wireless Network in Electric

The interference analysis provides a technology support for electric power communication access network construction and late operation and lays the foundations for popularization and application of

BBU Alarm Overview for LTE Systems

This document contains descriptions for 43 service affecting alarms reported by a base station. The alarms relate to issues with baseband units, RF units,

Troubleshooting Passive Intermodulation Problems in the Field

In the first example, 1750 MHz is one of the third order products and falls within the AWS-1 base station receive band. If the 1940 MHz and 2130 MHz carrier sources are physically close to each other, or

4G LTE Interference Location & Remediation Service

Locating 4G LTE uplink interference Over the course of 2013, LBA has seen an increase in the demand for 4G LTE base station interference

Demystifying Optical Transceiver Failures: Common

The Problem: While not always the transceiver's fault, the optical link loss exceeds the module's budget. Causes include: Dirty or damaged

LTE RF Channel Troubleshooting Guide

This document provides a troubleshooting guide for LTE RF channel faults. It describes common uplink and downlink channel faults such as uplink

Contact Us

For more information, pricing, or custom solutions, please contact us:

Website: <https://www.saastisfy.fr>

Email: sales@saastisfy.fr

Phone: +33 6 52 81 47 39

Address: 75 Rue de Rivoli, 75001 Paris, France

This document is for informational purposes only. Specifications subject to change without notice.

